



To reduce the temp. of MB1X0115---B and the features of low AC power, change some references(R502 R517 R523 R524 R526 C515 C517 V511 VD503 e.t.).